

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 11 Oct 2022

Preliminary Advice

Vehicle No	: XE6849T	Accident Date	: 30/08/2022
Make	: SCANIA G410LA4X2MSZ	Policy No.	: DMCG21013814
Assignment Date	: 05/10/2022	Excess	: S\$0.00
Date of Inspection	: 10/10/2022	Est. Duration of Repair	: 03 DAYS
Inspection At	: SCANIA SINGAPORE PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,286.51
Revised Amount	:S\$	3,286.51
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,286.51

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	252,000.00
COE / PARF Rebate	:S\$	20,613.00
Salvage Value	:S\$	
Margin for Repair	:S\$	231,387.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Vehicle pending for Investigation.

Please note that the preliminary advice amount (Revised) stated are subject to consistency check, part prices and labour cost.