Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Jenny Lew Date: 07 Feb 2023

Preliminary Advice

Insured Vehicle No : CB7503Z

TP Vehicle No : SNA5215T Accident Date : 03/10/2022

Make : TOYOTA PRIUS Assignment Date : 04/10/2022

Date of Inspection : 05/10/2022 Est. Duration of Repair : 14

Inspection At : MY CAR CONSULTANT PTE LTD (JALAN LAM HUAT) (HQ)

60 JALAN LAM HUAT, CARROS CENTRE #05-21

SINGAPORE 737869

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	84,938.40
Revised Amount	:S\$	21,794.84
Check Items (Estimated)	:S\$	10,474.00
Total	:S\$	32,268.84

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$
Pre-Accident Value :S\$
COE / PARF Rebate :S\$
Salvage Value :S\$
Margin for Repair :S\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly
		let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.