Date: 01/02/2023



 $51\; UBI\; AVE\; 1, \#02-25\; PAYA\; UBI\; INDUSTRIAL\; PARK, SINGAPORE\; 408933\;\; TEL: (065)\; 62563561\;\; FAX: (065)\; 62564315\;\; FAX: (065)\; 6256415\;\; FAX: (065)\;\; FAX: (065)\; 6256415\;\; FAX: (065)\;\; FAX: (065$

Immediate Advice

To: HSBC Life (Singapore) Pte. Ltd.

Survey Details:

Date of loss	30-Sep-2022	
Date of appointment	5-Oct-2022	
ate of survey 29-Nov-2022		
Location of survey	JOO HAK KEE AUTO PTE LTD	

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM	
Vehicle number	GBH9931M	
Make and Model	TOYOTA DYNA 150 5MT	
Date of registration		21-Nov-18
Market Value	\$	75,000.00
Parf Rebate	\$	18,069.00
Nett Loss	\$	56,931.00

Repair details:

,

Proposed/Revised repair cost:

Parts	\$ 1,383.50
Check items (estimate)	
Labour	\$ 1,430.00
Total	\$ 2,813.50
Lump Sum(if applicable)	\$ 2,250.00

Number of days for repair	\$	5.00 Est	
---------------------------	----	-----------------	--



 $51\,UBI\,AVE\,1, \#02-25\,PAYA\,UBI\,INDUSTRIAL\,PARK, SINGAPORE\,408933\,TEL: (065)\,62563561\,FAX: (065)\,62564315$

Remarks:

PIR AGAINST INSURED DRIVER FOR CARELESS DRIVING.				

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 2,430.00	(WITH 8% GST)
Loss of use	\$ 500.00	(5DAYS X\$100)
Loss of rental	NIL	no. of days
Loss of income	NIL	no. of days
LTA search fees	\$ 7.45	
Others	NIL	
Proposed Total	\$ 2,937.45	