

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte.
Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Hor, Yinrul

Date: 15 Nov 2022

Preliminary Advice

Vehicle No	: SMG377Y	Accident Date	: 02/10/2022
Make	: AUDI Q3 SPORTBACK	Policy No.	: 2070173151
Assignment Date	: 06/10/2022	Excess	: S\$0.00
Date of Inspection	: 05/10/2022	Est. Duration of Repair	: 5
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 44,756.00	(Estimate \$43,086.00 + SUpplementary \$1,670.00)
Revised Amount	:S\$ 15,501.00	
Check Items (Estimated)	:S\$ 15,470.00	
Total	:S\$ 30,971.00	
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value	:S\$ 163,000.00
COE / PARF Rebate	:S\$ 62,374.00
Salvage Value	:S\$
Margin for Repair	:S\$ 100,626.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.