



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0851/2022/EQ
DATE : 4-Oct-22
WIP : 44491

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 5/10/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

*Hi Adrian
8 days exclude 1 Sunday
15-Mar-23*

OWNER'S NAME : MS CHUA HUI LEE
ADDRESS : BLK 422 SERANGOON CENTRAL
#08-356
SINGAPORE 550422
TELEPHONE : HP +65 96727796
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070173151-01
VEHICLE NO : **SMG 377 Y**
MODEL CODE : AUDI Q3 SPORTBACK 1.4 TFS
MODEL YEAR : 16/12/2020
ENGINE NO : CZD C20424
CHASSIS NO : WAUZZZF32M1046753
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 2-Oct-22
PLACE OF ACCIDENT : BRADDELL ROAD, JUNCTION OF CROUCHER ROAD

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMG 377 Y

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00		
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00	\$	1,000.00
4	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND FRONT WHEEL ARCH TRIMS.	\$	3,000.00	\$	1,650.00
5	TO REMOVE AND RENEW LHS FRONT WHEEL SUSPENSION WITH SUBFRAME.	S/N \$	2,400.00	\$	2,400.00
TOTAL LABOUR CHARGES		:	\$ 8,680.00	\$	5,530.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMG 377 Y

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>C/F</i>		\$ 5,530.00
6	TO RENEW ALL FOUR RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$	640.00	\$ 640.00
7	TO REMOVE AND REINSTALL BODYKIT FOR THE AFFECTED PANELS.	S/N \$	780.00	\$ 250.00
8	Add labour	\$	1,670.00	\$ 1,670.00
9	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$	384.00	\$ 384.00
TOTAL LABOUR CHARGES		:	\$ 12,154.00	\$ 8,474.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMG 377 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 1,585.00	
2	FRONT BUMPER CLOSING ELEMENT - LH	1	\$ 66.00	
3	FRONT BUMPER CLOSING ELEMENT	1	\$ 212.00	
4	FRONT BUMPER SPOILER	1	\$ 850.00	\$ 679.60
5	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 171.00	
6	FRONT BUMPER TRIM - LH	1	\$ 182.00	
7	FRONT PARKING AID SENSOR SUPPORT - LH	1	\$ 29.00	
8	FRONT BUMPER GUIDE SECTION - LH	1	\$ 43.00	
9	FRONT FENDER - LH	1	\$ 1,445.00	\$ 1,156.00
10	FRONT FENDER ATTACHMENT PARTS	1	\$ 66.00	
11	FRONT FENDER BRACE - LH	1	\$ 98.00	
12	FRONT FENDER BRACKET - LH	1	\$ 39.00	
13	HEADLIGHT MOUNTING - LH	1	\$ 132.00	
14	HEADLIGHT - LH	1	\$ 5,952.00	
15	LIFY CYLINDER - LH	1	\$ 231.00	
16	LIFY CYLINDER HOSE	1	\$ 92.00	
17	FRONT WHEEL ARCH COVER - LH / RH	2	\$ 1,132.00	\$ 904.80
18	FRONT WHEEL HOUSING LINER - LH	1	\$ 260.00	\$ 208.00
19	FRONT WHEEL HOUSING LINER COVER - LH	1	\$ 18.00	
20	FRONT ASSEMBLY CARRIER	1	\$ 753.00	
SUB TOTAL SPARE PARTS			\$ 13,356.00	\$ 2,948.40

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMG 377 Y

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		C/F		\$	2,948.40
21	BONDED RUBBER BUSHES - UPPER / LOWER	1	\$	179.00	
22	LOWER ARM CONTROL - LH	1	\$	512.00	
23	FRONT WHEEL BEARING HOUSING - LH	1	\$	753.00	\$ 602.40
24	FRONT WHEELHUB BEARING - LH	1	\$	550.00	\$ 440.00
25	GUIDE JOINT- LH LOWER	1	\$	145.00	
26	COUPLING ROD	1	\$	105.00	
27	GAS SHOCK ABSORBER	1	\$	338.00	
28	FRONT DRIVE SHAFT - LH	1	\$	1,521.00	
29	STEERING RACK	1	\$	6,118.00	
30	STEERING TRACK ROD - LH	1	\$	99.00	\$ 78.56
31	FRONT STEERING TIE ROD END - LH	1	\$	126.00	\$ 100.40
32	LHS FRONT RIM	S/N	\$	2,000.00	\$ 2,000.00
33	RHS FRONT RIM	S/N	\$	2,000.00	\$ 2,000.00
34	LHS REAR RIM	S/N	\$	2,000.00	
35	RHS REAR RIM	S/N	\$	2,000.00	\$ 2,000.00
36	FRONT BUMPER COVER SPOILER	S/N		TBC	
37	SUPPLEMENTARY		\$	1,528.00	\$ 1,221.36
38	SUNDRIES		\$	800.00	\$ 148.96
TOTAL SPARE PARTS			:	\$	34,130.00
TOTAL LABOUR CHARGES			:	\$	12,154.00
GRAND TOTAL			:	\$	46,284.00
				\$	11,540.08
				\$	8,474.00
				\$	20,014.08

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-23/02/22



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0851/2022/EQ 14-Oct-22 CHANG 1 of 1 SMG 377 Y AUDI Q3 SPORTBACK 2.0	
Quantity	Description		Unit Price	Amount
Parts				
1	FRONT WHEEL BEARING HOUSING - RH	1	\$ 753.00	\$ 602.40
2	WHEEL BRARING WITH HUB - RH	1	\$ 550.00	\$ 440.00
3	TIE ROD END - RH	1	\$ 126.00	\$ 100.40
4	TRACK ROD - RH	1	\$ 99.00	\$ 78.56
GRAND TOTAL			\$ 1,528.00	\$ 1,221.36

For Premium Automobiles Pte Ltd

 Authorised Signature



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0851/2022/KS 14-Nov-22 CHANG 1 of 1 SMG 377 Y AUDI Q3 SPORTBACK 2.0	
Quantity	Description	Unit Price	Amount	
Labour				
1	To supply and install front bumper spoiler	\$ 480.00	\$ 480.00	
2	To carry out ceramic coating on affected area	\$ 1,190.00	\$ 1,190.00	
GRAND TOTAL		\$ 1,670.00	\$ 1,670.00	

For Premium Automobiles Pte Ltd

 Authorised Signature



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT