

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/CHI/0214/2022
DATE : 05-OCT-2022

AUTO & GENERAL INSURANCE (SINGAPORE) PTE LIMITED
190 CLEMENCEAU AVENUE
#03-01, SINGAPORE SHOPPING CENTRE
S(239924)
TEL : 62212199
FAX :
CLAIM DEPT

OWNER'S NAME : LIM TEIK CHENG
ADDRESS : 35 ENG KONG CRESCENT
#01-02
S(599427)
TELEPHONE NO : 9137 9352

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : P10342783R02 AUTO&GENERAL
VEHICLE NO : SFL4887Y
MODEL CODE : SJ5EK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20YC84243
CHASSIS NO : JF1SJ5KC5JG105528
MILEAGE : 1 KM
DATE IN : 05/10/2022
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 05/10/2022

Print Date : 05/10/2022
Print Time : 09:41:39

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SFL4887Y

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST LONPAC INS (YP3527Y)		
2	ZZ/001	DOA:01/10/2022 TIME:1505HRS LOCATION:PIE EXITING		
3	ZZ/002	REPLACE REAR BUMPER,BUMPER BEAM,END PANEL	1860.00	
4	ZZ/003	RESPRAY REAR BUMPER,BUMPER BEAM,END PANEL & TAILGATE	2160.00	
5	ZZ/004	TO CONDUCT WATER SEEPAGE TEST	100.00	
6	ZZ/005	TO CONDUCT (REAR) LIGHTING TEST	50.00	
7	ZZ/006	TO SUPPLY & INSTALL REVERSE SENSOR 2 EYES	300.00	
8	ZZ/007	FAULT DIAGNOSTIC (RESET)	280.00	
9	ZZ/008	SUNDRIES	100.00	
TOTAL LABOUR CHARGES			4850.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
 25 LENG KEE ROAD
 SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SFL4887Y

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
1	BUMPER FACE REAR FORESTER IL	57704SG012	1110.00			
2	BRKT SD R RH	57707SG080	29.60			
3	BRKT SD R LH	57707SG090	29.60			
4	BEAM COMPL R EU	57711SG0219P	592.00			
5	COVER HOOK R	57731SG010NN	29.60			
6	CLIP BMPR * 9 PCS	909140007	21.60			
7	CLIP *2 PCS	909140062				6.00
8	CARGO STEP PANEL S/S	E7710SG000	460.00			
SUB TOTAL			2272.40	0.00	0.00	6.00
LESS DISCOUNT (NETT-20 % S/LIST-30 %)			454.48	0.00	0.00	1.80
GRAND TOTAL			1817.92	0.00	0.00	4.20
OVERALL TOTAL			1822.12			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SFL4887Y

TOTAL LABOUR CHARGES	4850.00
TOTAL SPARE PARTS CHARGES	1822.12

GRAND TOTAL	6672.12 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the
affected vehicle. Should we require further labour
charges & spare parts in the process of repairs, we
shall inform you accordingly.