




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS3/SMO22009870/Uqy3m4 Date: 14/10/2022 Code: SMO	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SGB 2628H	Veh. Inspected	SJB 615Y	
Policy No.	D21MTPV01016005	Coverage (\$)	0.00	
Claim No.	CMTD2203582/MYE	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	06/10/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA STREAM (A)	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	JHMRN68408S200736	Colour	SILVER	
Odometer	256400 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	CONTINENTAL	6 mm	
L/H Front Tyre	205/55 R16	CONTINENTAL	6 mm	
R/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm	
L/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT PORTION.				
5. General Information				
Accident Date	05/10/2022	Inspect Date / Time	06/10/2022 (11:05 AM)	
Survey held at	3 MOTORWERKZ 25 KAKI BUKIT ROAD 4 SYNERGY @ KB #01-42 SINGAPORE 417800			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000-\$8,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		

Report Ref No. CS3/SMO22009870/Uqy3m4

Inspected By

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or
relying on this Report, in whole or in part, does so at his or her own risk.