

Date: 03/10/2022
 Vehicle No: SMS5846P
 Model: HYUNDAI AVANTE 1.6 GLS
 Chassis: KMHD841CMLU034261 - 2019
 Reg.Year: 2020

Not withstanding
Repair by pain
4 days

Third Party Insurer: CHINA TAIPING
 Third Party Veh No: GX6158E
 Date of Accident: 01/10/2022
 Estimator: KIT
 Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR RH	1		<i>By</i> \$1,993.70
2	FRONT DOOR SIDE MIRROR WITH COVER RH	1		<i>Car</i> \$281.50
3	FRONT DOOR WEATHERSTRIP RH	1		<i>By</i> \$145.80
4	FRONT BUMPER	1		<i>By</i> \$987.60
5	FRONT FENDER RH	1		REPAIR
6	FRONT SPORT RIM RH	1		REPAIR
SUB TOTAL				\$3,408.60
LESS 20%				\$681.72
PARTS TOTAL				\$2,726.88

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR BLACK TAPE STICKER RH	1		<i>Ma</i> \$50.00
S/N TOTAL				\$50.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS. \$500.00 *300*

LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS. \$700.00 *460*

TO TUFF KOTE & UNDERSEAL MATERIALS. \$100.00 *30*

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC. \$80.00 *20*

LABOUR TOTAL \$1,380.00

KIT TOTAL \$4,156.88