



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, Singapore 533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2002389349	Date of Loss:	28/09/2022
Vehicle Reg. No.:	SBA71R	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SEOW CHI HOU NELSON		
Make/Model:	HYUNDAI ELANTRA, 1.6 (A)	Vehicle Reg. Date:	15/08/2017
Vehicle Colour:	METALLIC RED		
Engine No:	G4FGHU687100	Chassis No:	KMHD841CMJU527392
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	KAN FOOK SING MOTOR WORKSHOP (DEFU)		

COST OF CLAIMS

	Amount
Parts	3,355.00
Miscellaneous Items	0.00
Labour	720.00
Paintwork Labour	720.00
Towing	0.00
Calculated Gross Total (S\$)	4,795.00
- Excess (S\$)	2,000.00
(S\$)	2,795.00
+ GST 7.00% (S\$)	195.65
Nett Amount (S\$)	2,990.65

This claim is handled by: MT TAN

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Oct 2022)
Parts: 143 HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Kan Fook Sing Motor Workshop/SBA71R/06/10/2022 12:38
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT HEADLAMP LH / <i>cut</i>	0.00	0.00	*400.00 F
2	1		*FRONT HEADLAMP LOWER BRACKET LH ?	0.00	0.00	*18.00 F
3	1		*FRONT SUPPORT PANEL ?	0.00	0.00	*310.00 F
4	1		*FRONT GRILLE ?	0.00	0.00	*450.00 F
5	1		*FRONT BUMPER / <i>re</i>	0.00	0.00	*350.00 F
6	1		*FRONT BUMPER SIDE RETAINER LH - BR	0.00	0.00	*22.00 F
7	1		*FRONT BUMPER TOP BRACKET LH ?	0.00	0.00	*40.00 F
8	10		*FRONT BUMPER CLIP / <i>re</i>	0.00	0.00	*25.00 F
9	1		*FRONT FENDER LH X <i>Repair</i>	0.00	0.00	*290.00 F
10	1		*FRONT FENDER SHIELD LH / <i>re</i>	0.00	0.00	*45.00 F
11	10		*FRONT FENDER SHIELD CLIP / <i>re</i>	0.00	0.00	*25.00 F
12	1		*FRONT DOOR LH X <i>Repair</i>	0.00	0.00	*680.00 F
13	1		*FRONT DOOR FAME STICKER 1 X <i>San</i>	0.00	0.00	*16.00 F
14	1		*FRONT DOOR FAME STICKER 2 X <i>San</i>	0.00	0.00	*16.00 F
15	1		*FRONT DOOR OUTER HANDLE LH / <i>cut</i>	0.00	0.00	*88.00 F
16	1		*FRONT SIDE MIRROR LH / <i>re</i>	0.00	0.00	*275.00 F

F=Franchise part.

Sub Total (S\$)	3,050.00
+ Margin on L,N Items 10.00% (S\$)	305.00
Total Parts (S\$)	3,355.00

Kan Fook Sing Motor Workshop/SBA71R/06/10/2022 12:38. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	SPRAYPAINTING CHARGES	New	700 720.00
Labour Items			
2	TO CHECK WIRING SYSTEM	New	30 50.00
3	TO CHECK ALIGNMENT	New	100 X 100.00
4	TO TRANSFER DOOR MECHANICISM TO NEW DOOR	New	50 X 50.00
5	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	450 520.00
Gross Labour Cost (S\$)			1,440.00

Kan Fook Sing Motor Workshop/SBA71R/06/10/2022 12:38. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Excess : 2000
Not Authorized.
Gao Qiang
6/10/22
5 Days.
P/P
before part photos.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for resurvey
- Parts price to be confirmed
- Third party claims on "No Prejudice" basis
- No legal liability to be accepted
- Supplier to be confirmed and surveyed and is subject to the insurance company

Acknowledged by Repairer

Signature:

Date: