



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : HSBC LIFE (SINGAPORE) PTE LTD

12/5/2023

Survey Details:

Date of loss	29-Sep-22
Date of appointment	5-Oct-22
Date of survey	6-Oct-22
Location of survey	ERZAT LEE MOTOR TRADING PTE LTD

Vehicle Details:

Claim Type:	Third Party Claim
Vehicle number	FBD 4452H
Make and Model	YAMAHA SPARK 135
Date of registration	6/3/2009
Excess	-
Market Value	\$ 8,000.00
Parf Rebate	\$ 2,081.00
Nett Loss	\$ 5,919.00

Repair details:

Initial Estimate	\$ 5,323.50
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 2,062.20
Check items (estimate)	
Labour	\$ 300.00
Total	\$ 2,362.20
Lump Sum(if applicable)	\$ 1,900.00

Number of days for repair	<u>3</u>
---------------------------	----------



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

DAMAGES CONSISTENT.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	