

Vehicle Damage Assessment Report for [SHB1336U]

Estimate Created: 13/11/2022 23:17 by Insurlogic 1 (Insurlogic_Pte_Ltd)

Owned: 14/04/2023 06:58 by Insurlogic 5 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	Ergo Insurance	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Toyota	Model	Prius
Engine Type			
License Plate Number	SHB1336U	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$850.00 WITH 2 WORKING
DAYS

Insurlogic 5 (14/04/2023 06:58)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
FRONT BUMPER		1	420.23	0.00 %	420.23
EMBELM ASSY FRT		1	74.03	0.00 %	74.03
FRONT BUMPER CLIPS		1	36.00	0.00 %	36.00
Parts Subtotal					530.26

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
NUMBER PLATE		1.0	35.00	0.00 %	35.00
Materials Subtotal					35.00

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
REPLACE/ REPAIR ACCIDENT AFFECTED ITEMS AND AREAS	RnR	200.00	0.00 %	200.00

Paint

Description		Paint Type	Cost	Markup/Disc %	Price
PAINT FRONT BUMPER		Full spray	200.00	0.00 %	200.00
Labor Rate	S\$ 50 / Hour			General Labor Subtotal	200.00
				Paint Labor Subtotal	200.00
				Labor Subtotal	400.00

Summary

Repair Cost	965.26
Discount(10 %)	(96.53)
	868.73
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	868.73