

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0782/2022/EQ
DATE : 8-Sep-22
WIP : 41041

Xiao Chen.

05 Days.

\$4166.40.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 6/10/2022

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept.

OWNER'S NAME : MR WONG EE KAY GEOFFREY
ADDRESS : 33 BIN TONG PARK
SINGAPORE 269814

TELEPHONE : HP +65 97236646
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220082881
VEHICLE NO : SNH 25 X
MODEL CODE : AUDI Q7 3.0 TFSI QU TIPTR
MODEL YEAR : 28/7/2022
ENGINE NO : DCB 531578
CHASSIS NO : WAUZZZ4MXD022969
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 6-Sep-22
PLACE OF ACCIDENT : LENG KEE ROAD & ALEXANDRA ROAD

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNH 25 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$ 360.00	X
2	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 900.00	X 300 ✓
3	TO DISMANTLE AND REINSTALL REAR BUMPER. TO REPAIR RHS REAR FENDER. TO RENEW RHS FRONT DOOR AND RHS REAR DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,000.00	600 ✓
4	TO RESPRAY REAR UPPER BUMPER, REAR LOWER BUMPER, RHS REAR FENDER, RHS REAR DOOR, RHS FRONT DOOR, 2 DOOR COVERS, DOOR HANDLES, RHS REAR DOOR WHEEL ARCH TRIM AND BOTH REAR WHEEL ARCH TRIMS.	\$ 7,000.00	1900 ✓ Door x 2 = 1200 Door Protector x 2 = 400 Door Arc = 100 Fender Arc = 200 <u>1900</u>
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		\$ 12,452.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNH 25 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT DOOR - RH <i>Regis</i>	1	\$ 5,466.00	+
2	FRONT OUTER DOOR SEAL	1	\$ 282.00	+
3	BONDING AGENT	1	\$ 51.00	+
4	CLEANING SOLUTION	1	\$ 74.00	+
5	APPLICATOR	1	\$ 9.00	+
6	FRONT DOOR CATCH - RH	1	\$ 137.00	+
7	FRONT DOOR COVER - RH <i>Regis</i>	1	\$ 963.00	+
8	REAR DOOR - RH <i>Regis</i>	1	\$ 5,708.00	+
9	BONDING AGENT	1	\$ 51.00	+
10	CLEANING SOLUTION	1	\$ 74.00	+
11	APPLICATOR	1	\$ 9.00	+
12	REAR DOOR CATCH - RH	1	\$ 137.00	+
13	REAR OUTER DOOR SEAL - RH <i>Regis</i>	1	\$ 213.00	+
14	REAR WEATHER STRIP	1	\$ 282.00	+
15	REAR DOOR COVER - RH <i>cut</i>	1	\$ 883.00	706
16	REAR DOOR WHEEL COVER - RH <i>cut</i>	1	\$ 201.00	160.40
17	REAR WHEEL COVER - LH / RH <i>RH cut</i>	2	\$ 770.00	385 308
18	SUNDRIES <i>Not Rec.</i>		\$ 400.00	?X
TOTAL SPARE PARTS		:	\$ 15,710.00	
TOTAL LABOUR CHARGES		:	\$ 12,452.00	
GRAND TOTAL		:	\$ 28,162.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.