



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

STRIDES AUTOMOTIVE SERVICES PTE LTD
60 WOODLANDS INDUSTRIAL PARK
E4SINGAPORE 757705

Ref: CS/SMR22009920/Eqy3e2

Date: 10/11/2022

Code: SMR

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 690C	Veh. Inspected	SLC 3335G
Policy No.		Coverage (\$)	0.00
Claim No.	TAX/10/22/2013	Excess (\$)	0.00
Assign From	HUA YEN	Assign Date	07/10/2022

2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN GOLF	c.c	1395
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WVWZZZAUZKW015563	Colour	BLUE
Odometer	93275 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/50 R16	GOODYEAR	4 mm
L/H Front Tyre	205/50 R16	GOODYEAR	4 mm
R/H Rear Tyre	205/50 R16	GOODYEAR	4 mm
L/H Rear Tyre	205/50 R16	GOODYEAR	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/10/2022	Inspection Date	10/10/2022
Survey held at	VOLKSWAGEN CENTRE SINGAPORE 247 ALEXANDRA ROAD SINGAPORE 159934		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **7 Working Days**