



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CS3/CTI22002439/Gqy3e2-1	
			Date: 28/10/2022	
			Code: CTI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBB 8840E	Veh. Inspected	AZ 5555J	
Policy No.	DMCVSNA00012982200	Coverage (\$)	0.00	
Claim No.	SNM22D201791/C02	Excess (\$)	0.00	
Assign From	Adeline Chng	Assign Date	05/10/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA ADV750	c.c	745	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	JH2RH10A1MK013551	Colour	RED	
Odometer	9640 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	120/70 R17	BRIDGESTONE	8 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	160/60 R15	BRIDGESTONE	8 mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	14/03/2022	Inspection Date	16/03/2022	
Survey held at	ONG MOTOR TRADING NO. 464 MACPHERSON ROAD SINGAPORE 368182			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>4 Working Days</b>	