

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

mate

2022

FIRST CAPITAL INSURANCE LTD
Robinson Road
#16-01 City House
Singapore 068877.

Attention :- XA026

Page # :- 1

Veh # :- SJP9247T

Veh Model :- HYUNDAI AVANTE

Estimate# :- CK424114

Claim # :-

ACC. Date :- 05/10/22

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	BONNET / <i>DD</i>	1 PC	1,885.10	1,885.10
2.	FRONT FENDER LH/RH <i>x BR</i>	2 PC	525.20	1,050.40
3.	HEADLAMP LH/RH <i>BR</i>	2 PC	550.00	1,100.00
4.	RADIATOR GRILLE <i>BR</i>	1 PC	380.00	380.00
5.	RADIATOR GRILLE CLIPS <i>ne</i>	10 PC	3.00	30.00
6.	HYUNDAI LOGO <i>ne</i>	1 PC	45.30	45.30
7.	FRONT BUMPER <i>BR</i>	1 PC	580.40	580.40
8.	FRONT BUMPER CLIPS <i>ne</i>	10 PC	3.00	30.00
9.	FRONT BUMPER RETAINER LH/RH <i>BR</i>	2 PC	35.80	71.60
10.	FRONT BUMPER LOWER AIR GRILLE <i>BR</i>	1 PC	85.00	85.00
11.	SUPPORT PANEL <i>BR</i>	1 PC	895.90	895.90
12.	BUMPER REINFORCEMENT <i>BR</i>	1 PC	350.00	350.00
13.	A/C CONDENSER <i>BT</i>	1 PC	990.90	990.90
14.	RADIATOR <i>BT</i>	1 PC	788.40	788.40
15.	REAR BOOT LID <i>DD</i>	1 PC	1,350.10	1,350.10
16.	REAR BOOT LID HINGE LH/RH <i>x R</i>	2 PC	145.00	290.00
17.	BOOT LID LOCK <i>BT</i>	1 PC	120.00	120.00
18.	AVANTE EMBLEM <i>ne</i>	1 PC	35.80	35.80
19.	HYUNDAI LOGO <i>ne</i>	1 PC	45.90	45.90
20.	S EMBLEM <i>ne</i>	1 PC	89.50	89.50
21.	TAILLAMP LH/RH <i>CU</i>	1 PC	388.40	776.80
22.	BOOT LID LAMP LH/RH <i>CU</i>	1 PC	189.60	379.20
23.	REAR BUMPER <i>BR</i>	1 PC	689.10	689.10
24.	REAR BUMPER CLIPS <i>ne</i>	10 PC	3.00	30.00
25.	REAR BUMPER RETAINER LH/RH <i>BR</i>	2 PC	48.50	97.00
26.	REAR FENDER LH (REPAIR) <i>x R</i>	1 PC		
27.	REAR FENDER RH <i>y R</i>	1 PC		
28.	REAR END PANEL <i>DD</i>	1 PC	1,806.70	1,806.70
29.	END PANEL TRIM <i>BR</i>	1 PC	589.80	589.80
30.	REAR BUMPER REINFORCEMENT <i>BR</i>	1 PC	39.50	39.50
31.	REAR BUMPER REINFORCEMENT BRKT <i>BT</i>	1 PC	389.50	389.50
32.	REAR BUMPER SPONGE <i>BR</i>	1 PC	35.00	35.00
33.	REAR BUMPER REINFORCEMENT SIDE BRKT LH/RH <i>BT</i>	1 PC	180.00	180.00
		2 PC	85.30	170.60
LIST TOTAL S\$				15,397.50
20% DISCOUNT S\$				-3,079.50
				12,318.00
SPECIAL NET ITEMS :				
1.	FRONT NUMBER PLATE <i>BR</i>	1 PC	40.00	40.00
2.	COOLANT <i>ne</i>	1 PC	60.00	60.00
3.	A/C GAS <i>ne</i>	1 PC	50.00	50.00
4.	REVERSE SENSOR <i>BR</i>	1 PC	200.00	200.00
SPECIAL NET TOTAL S\$				350.00

LABOUR :
bizSAFE TO KNOCK & STRAIGHTEN FRONT HEADLAMP PANEL,
TO REALIGN FRONT LH/RH SIDE FENDER, FRONT

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0688864-2

Page # :- 1 147235

Veh # :- SJP9247T

Veh Model :- HYUNDAI AVANTE

Estimate# :- CK424114

Claim # :-

ACC. Date :- 05/10/22

Terms :- C.O.D Days

Remarks :-

ate

22

RST CAPITAL INSURANCE LTD
Robinson Road
#01 City House
Singapore 068877.

Attention :- XA026

No.	Description	Qty	U.Price	Amounts S\$
	SUPPORT PANEL. TO REPLACE FRONT ACCIDENT DAMAGES PARTS. REALIGN ALL CONNECTION		800	1,100.00
	TO SPRAY PAINT ON FRONT BONNET, BOTH LH/RH FENDER, FRONT BUMPER & REINFORCEMENT		800	850.00
	TO KNOCK & STRAIGHTEN LH REAR FENDER. TO REPLACE TAILGATE, RH FENDER, BUMPER. TO CUT/ WELD/ KNOCKING REAR END PANEL		1100	1,300.00
	TO SPRAY PAINT ON TAILGATE, REAR BUMPER, RH REAR FENDER, END PANEL, BOOT FLOOR, LH FENDER		1000	1,100.00
	TP APPLY ANTI RUST PROOFING ON AFFECTED AREAS		30	180.00
	TO RPELACE A/C CONDENSER & RADIATOR		50	180.00
	TO ADJUST FOCUS HEADLAMP		30	80.00
	TO APPLY BODY JOINT SEALANT ON CUTTING AREAS		30	80.00
	TO REMOVE & REFIT REAR BOOT UPHOLSTERY, SIDE TRIM/ COVERING, ENDP ANEL COVER & INNER TRIM TO ASSIST REPAIR		50	80.00
	TO TRANSFER REAR BOOT LID, LOCK MECHANISM, WIRING HARNESS & RELATED TO NEW UNITS		30	80.00
	TO INSTALL PARKING SENSOR & CHECK FUNCTIONING		30	80.00
	TO CHECK FOR AND RECTIFY WIRING FAULT. TO CONDUCT DIAGNOSTICS CHECK & RESET SYSTEM AFTER REPAIR		X	180.00
	LABOUR TOTAL S\$			5,290.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 17,958.00

GST @ 7 % 1,257.06

AMOUNT DUE S\$ 19,215.06

Acknowledged by Repairer

Signature:

Date:

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**