



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: OH VALE			Ref: CS3/ASM22009935/Ecy3e2 Date: 17/11/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 9196J	Veh. Inspected	SKZ 4694D
	Policy No.	VFX/P2419140	Coverage (\$)	0.00
	Claim No.	S2M04C38	Excess (\$)	0.00
	Assign From	OH VALE	Assign Date	07/10/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ALTIS	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	MR053REH104543673	Colour	GREY
	Odometer	152270 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	MICHELIN	4 mm
	L/H Front Tyre	205/55 R16	MICHELIN	4 mm
	R/H Rear Tyre	205/55 R16	MICHELIN	4 mm
	L/H Rear Tyre	205/55 R16	MICHELIN	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	30/09/2022	Inspection Date	10/10/2022
	Survey held at	LENG YONG MOTOR WORKSHOP 27-A JURONG PORT ROAD #01-28 JTC IND SERVICE CENTRE SINGAPORE 619101		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	