

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305532284
Date : 19.10.2022

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

FINALIZATION FORM

To : LKK

Fax :

Attn : GUO QIANG

Vehicle Reg No. : SHA8228H

07.10.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- Z The repair job shall bill to: TOKIO SML2594Y
2. The finalized amount shall be:
- | | |
|---|-------------------|
| (a) Spare Parts after List discount | <u>\$801.12</u> |
| (b) Labour Charges | <u>\$651.00</u> |
| Total for Part-By-Part Repair Cost | <u>\$1,452.12</u> |
| (c.) Lumpsum Repair (if applicable) | |
| Total for Lumpsum repair cost after Less: | |
| Final Lumpsum Repair cost | |

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature : 

Signature : _____

Name : CHIANG

Name : _____

Tel : 62148314

Date : _____

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 11.10.2022

Time: 15:41:13

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305532284
REGN NO : SHA8228H
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 31.08.2021
DATE/TIME IN : 07.10.2022 16:30
ACCIDENT DATE : 07.10.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52
0002 04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00
0003 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10	22.00	20.00	17.60
0004 28-01-0104-2029-A	VEHICLE NUMBER PLATE REAR	1	55.00	2.00-	55.00

SUB-TOTAL : 801.12

JOB NATURE

0000 PB	PANEL BEATING SHA8228H TP	350.00
0001 SP	SPRAYPAINT CHARGE	250.00
0002 20-05	REMOVE/REFIX REVERSE SENSOR	40.00
0003 L	MERIMEN FEE	11.00

SUB-TOTAL : 651.00

Total: \$1452.12