

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CCPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	07/10/2022
Vehicle Reg. No.:	SHA8228H	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Vehicle Reg. Date:	31/08/2021
Vehicle Colour:	YELLOW	Gen Condition:	GOOD
Engine No:	G4LEKU387388	Chassis No:	KMH851CVLU183667
Odometer:	155984 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	1,386.24
Miscellaneous Items	11.00
Labour	910.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,307.24
+ GST 7.00% (S\$)	161.51
Nett Amount (S\$)	2,468.75

This claim is handled by: CHIANG LIAT CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 08 Oct 2022)**Parts:** 143 HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHA8228H/08/10/2022 08:44**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER <i>✓ RL</i>	20.00	0.00	*459.40 FL
2	1		*REAR BUMPER CENTRE LOWER MOULDING <i>✓ CA</i>	20.00	0.00	*451.25 FL
3	1		*REAR BUMPER REINFORCEMENT <i>?</i>	20.00	0.00	*394.80 FL
4	10		*REAR BUMPER CLIPS <i>✓ RL</i>	20.00	0.00	*22.00 FL
5	2		*REAR BUMPER BRACKET LH/RH <i>X</i>	20.00	0.00	*111.60 FL
6	1		*REAR BUMPER REVERSE SENSOR <i>X</i>	0	0.00	*180.00 FS
7	1		*REAR NUMBER PLATE W/HOLDER <i>✓ Sub</i>	0	0.00	*55.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	1,674.05
- List Item Discount on L Items (S\$)	287.81
Total Parts (S\$)	1,386.24

ComfortDelGro Engineering Pte Ltd/SHA8228H/08/10/2022 08:44. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	250 550.00
2	SPRAY PAINTING	New	250 300.00
3	REMOVE/REFIX REVERSE SENSOR	New	40 60.00
Gross Labour Cost (S\$)			910.00

ComfortDelGro Engineering Pte Ltd/SHA8228H/08/10/2022 08:44. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

28 days
P/S
Can of
10/10
3pm

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged parts during resurvey
- Parts price to be based on market information
- Third party to be based on "without Prejudice" basis
- No illegal or unethical practices allowed
- Supplier to be based on lowest cost received and
is submitted to the relevant Insurance Company

Acknowledged by Rep:

Signature:

Date: