

Estimation

Date: 10/10/2022

Vehicle: SND2016E

Make / Model: TOYOTA ALTIS

Chassis No: AXA

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	BOOTLID <i>repmv</i>	1	\$ 1,024.00	\$ 1,024.00 <i>XR</i>
2	BOOTLID EMBLEM 'ALTIS' <i>m</i>	1	\$ 65.00	\$ 65.00 <i>✓</i>
3	BOOTLID SENSOR <i>XNA</i>	1	\$ 312.00	\$ 312.00 <i>X</i>
4	BOOTLID EMBLEM 'COROLLA' <i>m</i>	1	\$ 65.00	\$ 65.00 <i>✓</i>
5	REAR BUMPER <i>de</i>	1	\$ 698.00	\$ 698.00 <i>542</i>
6	REAR BUMPER SIDE RETAINER <i>Xm</i>	2	\$ 112.00	\$ 224.00 <i>X</i>
7	REAR BUMPER BRACKET <i>Xm</i>	2	\$ 168.00	\$ 326.00 <i>X</i>
8	REAR BUMPER SENSOR <i>? Xm</i>	2	\$ 381.00	\$ 762.00 <i>X</i>
9	REAR BUMPER REINFORCEMENT <i>? X</i>	1	\$ 395.00	\$ 395.00 <i>332.70</i>
10	REAR BUMPER REFLECTOR <i>Xm</i>	2	\$ 112.00	\$ 224.00 <i>X</i>
	<i>1004.70</i>			\$ 4,095.00
	<i>25%</i>		Less 25%	\$ 1,023.75
	<i>753.52</i>		Total	\$ 3,071.25

S/Nett items:				
1	BOOTLID INSULATOR CLIPS <i>XNA</i>	1	\$ 30.00	\$ 30.00 <i>X</i>
2	REAR BUMPER CLIPS <i>m</i>	1	\$ 40.00	\$ 40.00 <i>30</i>
				\$ 3,060.00
Labour to: Rear				
1	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 500.00	\$ 500.00 <i>400</i>
2	PANEL BEATING ON AFFECTED AREAS	1	\$ 500.00	\$ 500.00 <i>300</i>
3	TO CHECK ELECTRICAL WIRING	1	\$ 100.00	\$ 100.00 <i>40</i>
4	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 50.00	\$ 50.00 <i>Xm</i>
				\$ 1,150.00
			Parts Replacement Amount	\$ 6,131.25
			Total Amount for Labour	\$ 1,150.00
			Total Amount	\$ 7,281.25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

753.52
30.00
740.00
1523.52
20%
1218.81
45- \$1,200 / 3 days
Resurvey after repair
Resm
Hp 90010068
3 days
L/S
10/10/22 @ 1630