

Immediate Advice

To: AXA Insurance Pte Ltd 15/11/2022

Survey Details:

Date of loss	6-Oct-22	
Date of appointment	10-Oct-22	
Date of survey	10-Oct-22	
Location of survey	TICK HAI MOTOR & WELDING S	SERVICES

Vehicle Details:

Claim Type:	Third Part	Third Party Claim		
Vehicle number	SCL 6886\	1		
Make and Model	TOYOTA C	TOYOTA CAMRY 2.0 AUTO ABS AIRBA		
Date of registration	30/3/200	9		
Excess	-			
Market Value	\$	50,000.00		
Parf Rebate	\$	20,395.00		
Nett Loss	\$	29,605.00		

Repair details:

Initial Estimate	\$ 18,236.65

Proposed/Revised repair cost:

Parts	\$ 8,994.33
Check items (estimate)	\$ -
Labour	\$ 2,270.00
Total	\$ 11,264.33
Lump Sum(if applicable)	\$ 9,000.00

Number of days for repair	<u>6</u>



51 UBI AVE 1, #91-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

Damages consistent.		

Mandate:

Liability(TP)	%]
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	