



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

STRIDES AUTOMOTIVE SERVICES PTE LTD
60 WOODLANDS INDUSTRIAL PARK
E4SINGAPORE 757705

Ref: CS/SMR22009983/Eqy3m4

Date: 25/10/2022

Code: SMR

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMB 1605J	Veh. Inspected	SBS 6326Y
Policy No.		Coverage (\$)	0.00
Claim No.	BUS/10/22/5010	Excess (\$)	0.00
Assign From	HUA YEN	Assign Date	10/10/2022

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ CITARO O530	c.c	6374
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	WEB62808323123806	Colour	MULTI COLOUR
Odometer	601307 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	295/80 R22.5	BRIDGESTONE	4 mm
L/H Front Tyre	295/80 R22.5	BRIDGESTONE	4 mm
R/H Rear Tyre	295/80 R22.5	BRIDGESTONE	4 mm
L/H Rear Tyre	295/80 R22.5	BRIDGESTONE	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	09/10/2022	Inspection Date	11/10/2022
Survey held at	TOWER TRANSIT SINGAPORE PTE. LTD. 21 BULIM DRIVE SINGAPORE 648170		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------