

# ESTIMATED ACCIDENT REPAIR COST



ACCIDENT TIME REPORTED	07:14HRS
ACCIDENT DATE	09-Oct-22
BUS CAPTAIN NAME	PETER CHEN SIAO HUI
THIRD PARTY CLAIM AGAINST	SMRT BUS / MSFCL

BUS REG. NUMBER	SBS6326Y
BUS TYPE (SD/DD)	SD
BUS ROUTE NUMBER	
BUS ADVERTS (Y/N)	N

## SECTION 1 : MATERIALS, PARTS & CONSUMABLE ITEMS

NO.	Part or Item Description	Quantity	Total Cost
1	OS TAIL LAMP / RK	1	\$ 949.12
2	OSR BUMPER (CITARO) / RK	1	\$ 746.18
3	FOGLIGHT (LAMP) / RK	1	\$ 60.22
4	SIDE MARKER LIGHT / 1/1	1	\$ 74.60
5	DOWEL (ANCHOR) / RK	1	\$ 4.40
		7% GST	\$ 128.42
		<b>PARTS TOTAL COST</b>	<b>\$ 1,962.94</b>

1834.52 ~~1902.94~~  
 -10% ~~10%~~  
 1651.07 ~~1700.04~~

## SECTION 2 : LABOUR COST - ASSESSMENT / REPAIR / SPRAY PAINT

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)	TOTAL COST
TO DISMANTLE & REPLACE :- • ITEM NOS 1 - 5	650 \$ 1,950.00
TO REMOVE & INSTALL PARTS AND TO PERFORM REPAIR WORKS :- • RADIATOR FLAP ACCESS DOOR	1275 X \$ 975.00
SPRAY PAINTING :- • RADIATOR FLAP ACCESS DOOR • OSR CORNER BUMPER	\$ 1,280.00
SPRAY PAINTING \$640 PER PANEL LABOUR CHARGES \$650 PER DAY	1930 7% GST \$ 294.35
	<b>LABOUR TOTAL COST</b> \$ 4,499.35

P/P total - ~~3090.04~~  
3581.07

## SECTION 3 : NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

Steve (LKK)  
11/10/22, 10.00am  
m n  
3 days

DATE IN	9-Oct-2022
DATE & TIME SURVEY	
DATE OUT	
TOTAL NUMBER OF DAYS	

BUS TYPE (SD / DD)	SD
LOSS OF USE COST	

M RL y  
PIP

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

SUMMARY	
SECTION NO.	COST
1	\$ 1,962.94
2	\$ 4,499.35
3	\$ -
<b>TOTAL</b>	<b>\$ 6,462.29</b>

Acknowledged by Repairer  
Signature:  
Date: