

ESTIMATED ACCIDENT REPAIR COST



ACCIDENT TIME REPORTED	07:14HRS
------------------------	----------

BUS REG. NUMBER	SBS6326Y
-----------------	----------

ACCIDENT DATE	09-Oct-22
---------------	-----------

BUS TYPE (SD/DD)	SD
------------------	----

BUS CAPTAIN NAME	PETER CHEN SIAO HUI
------------------	---------------------

BUS ROUTE NUMBER	
------------------	--

THIRD PARTY CLAIM AGAINST	SMRT BUS / MSFCL
---------------------------	------------------

BUS ADVERTS (Y/N)	N
-------------------	---

SECTION 1 : MATERIALS, PARTS & CONSUMABLE ITEMS

NO.	Part or Item Description	Quantity	Total Cost
1	OS TAIL LAMP	1	\$ 949.12
2	OSR BUMPER (CITARO)	1	\$ 746.18
3	FOGLIGHT (LAMP)	1	\$ 60.22
4	SIDE MARKER LIGHT	1	\$ 74.60
5	DOWEL (ANCHOR)	1	\$ 4.40
		7% GST	\$ 128.42
		PARTS TOTAL COST	\$ 1,962.94

SECTION 2 : LABOUR COST - ASSESSMENT / REPAIR / SPRAY PAINT

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)	TOTAL COST
TO DISMANTLE & REPLACE :- • ITEM NOS 1 - 5	\$ 1,950.00
TO REMOVE & INSTALL PARTS AND TO PERFORM REPAIR WORKS :- • RADIATOR FLAP ACCESS DOOR	\$ 975.00
SPRAY PAINTING :- • RADIATOR FLAP ACCESS DOOR • OSR CORNER BUMPER	\$ 1,280.00
SPRAY PAINTING \$640 PER PANEL LABOUR CHARGES \$650 PER DAY	7% GST \$ 294.35
	LABOUR TOTAL COST \$ 4,499.35

SECTION 3 : NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

	DATE IN	9-Oct-2022
	DATE & TIME SURVEY	
	DATE OUT	
	TOTAL NUMBER OF DAYS	
BUS TYPE (SD / DD)	SD	
LOSS OF USE COST		

SUMMARY	
SECTION NO.	COST
1	\$ 1,962.94
2	\$ 4,499.35
3	\$ -
TOTAL	\$ 6,462.29