

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 10 Oct 2022)
Parts: N/A NISSAN CABSTAR 3.0 5MT ABS 2DR 2WD EURO 5 (A) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Strides Automotive Services Pte Ltd/GBB9188Z/10/10/2022 15:15
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page.
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*ENGINE WIRE HARNESS <i>? burnt /</i>	0.00	0.00	*3,307.86 F
2	1		*ALTERNATOR <i>? burnt /</i>	0.00	0.00	*2,482.51 F
3	1		*AIR CON COMPRESSOR <i>? burnt /</i>	0.00	0.00	*1,638.87 F
4	1		*ENGINE SEAT COVER INSULTOR <i>burnt /</i>	0.00	0.00	*746.00 F

F=Franchise part.

Sub Total (S\$)

8,175.24

- Add. Disc. on L,N Items 10.00% (S\$)

817.52

Total Parts (S\$)

7,357.72 ✓

Strides Automotive Services Pte Ltd/GBB9188Z/10/10/2022 15:15. Not valid without Reference section.

Generated using Merlimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Miscellaneous Items

1 1 OD/TP Case (Insurer)

Amount

11.00

Sub Total (\$\$)

11.00

Estimates on Labour

No Particulars

Lab.Type Amount

Labour Items

1	REPLACE ENGINE COMPARTMENT DAMAGE PART DUE TO FIRE	New	200	1,000.00
2	TO CHECK WIRING AND OTHER ENGINE COMPARTMENT ELECTRICAL SYSTEM IS IT DAMAGE DUE TO FIRE	New	150	350.00
3	TOP-UP AIR CON GAS (FLASH SYSTEM AND TOP UP AIR CON OIL)	New	100	150.00
4	SUNDRIES	New	20	100.00
5	BATTERY	New	AN X	200.00

Gross Labour Cost (\$\$) 1,800.00

Strides Automotive Services Pte Ltd/GBB9188Z/10/10/2022 15:15. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third Party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair

HP 90010068

3 days

L/S

11/10/22 @ 1530

EXCESS: TBA

Revert

Repair after repair

Repair limit

= \$6000