

(SUPPLEMENTARY)

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2002752224-01	Date of Loss:	08/10/2022
Vehicle Reg. No.:	SMU4897M	Driveable?	
Driver Age/Info:	23 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	ALVIN TAN YANG HAI	Contact No:	+6596750429
Driver:	JAMIE TAN (CHEN SHENGWEI)		
Make/Model:	BMW 523I, 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A)	Vehicle Reg. Date:	28/12/2010
Vehicle Colour:	BLACK		
Engine No:	06017631N52B25AF	Chassis No:	WBAFP32070C547508
Odometer:	123347 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	18		
Description of Accident/Loss	REFER TO SAS.		
Present Location:	FALCON-AIR AUTO SERVICES PTE LTD (SIN MING)		

COST OF CLAIMS	Amount
Parts	63.80
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	63.80
+ GST 7.00% (\$\$)	4.47
Nett Amount (\$\$)	68.27
+ Previous Estimates (\$\$)	22,831.23
Claim Total (\$\$)	22,899.50

Reference

Parts:	143	BMW 523i 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A) (Catalogue:Merimen Singapore 1.0)
---------------	-----	--

Print Code: Falcon-Air Auto Services Pte Ltd/SMU4897M/20/12/2022 13:18

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER SEAL	tn	0.00	0.00
2	1		*BONNET STOPPER	dd	0.00	0.00
F=Franchise part.						
Sub Total (\$)						58.00
+ Margin on L,N Items 10.00% (\$)						5.80
Total Parts (\$)						63.80

Falcon-Air Auto Services Pte Ltd/SMU4897M/20/12/2022 13:18. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Falcon-Air Auto Services Pte Ltd/SMU4897M/20/12/2022 13:18. Not valid without Reference section.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

FALCON-AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg