



DICKSON GROUP

Your Trusted Automotive Solutionist

DICKSON AUTO CARE CENTRE PTE LTD
29 UBI ROAD 4, DICKSON AUTO CENTRE
SINGAPORE 408619
TEL: 6668 1122 | FAX: 6668 1123

QUOTATION

QUOTATION FOR

NAME: MSIG Insurance (Singapore) Pte. Ltd
COMPANY NAME: MSIG Insurance (Singapore) Pte. Ltd
STREET ADDRESS: 4 Shenton Way, #21-01 SGX Centre Two
POSTAL CODE: Singapore 068807
PHONE: 6827 2888

DATE: 7/10/2022

REF: SNA9222X
VEHICLE NO.: SNA9222X
MAKE: BMW
MODEL: X5
PREPARED BY: POON

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
LABOUR							
1	TO REMOVE & REFIT ALL LIGHTING & WIRING	1		\$100.00	\$ 100.00		\$ 100.00
2	TO REMOVE & REFIT REVERSE SENSORS	1		\$200.00	\$ 200.00		\$ 200.00
3	TO REMOVE & REFIT REAR WINDSCREEN	1		\$200.00	\$ 200.00		\$ 200.00
4	TO REMOVE & REFIT EXHAUST PIPE & REALIGN	1		\$280.00	\$ 280.00		\$ 280.00
5	TO PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS & PANELS, CUT & WELD IF NECESSARY AND REALIGN	1		\$1,000.00	\$ 1,000.00		\$ 1,000.00
6	TO PROVIDE SKILL LABOUR TO PAINT ALL NEW PARTS & PANELS	1		\$1,000.00	\$ 1,000.00		\$ 1,000.00
PARTS							
1	TAIL GATE	1		\$6,160.55	\$ 6,160.55		\$ 6,160.55
2	TAIL GATE UPPER PROTECTOR	1		\$330.50	\$ 330.50		\$ 330.50
3	TAIL GATE LOWER PROTECTOR	1		\$253.30	\$ 253.30		\$ 253.30
4	TAIL GATE REFLECTOR LH & RH	1		\$65.60	\$ 65.60		\$ 65.60
5	TAIL GATE LOGO	1		\$95.85	\$ 95.85		\$ 95.85
6	TAIL GATE X5 LOGO	1		\$65.60	\$ 65.60		\$ 65.60
7	REAR BUMPER	1		\$1,980.90	\$ 1,980.90		\$ 1,980.90
8	REAR BUMPER CLIPS	10		\$3.00	\$ 30.00		\$ 30.00
9	REAR BUMPER SIDE RETAINER LH & RH	2		\$152.80	\$ 305.60		\$ 305.60
10	REAR BUMPER TOWING COVER	1		\$63.95	\$ 63.95		\$ 63.95
11	REAR BUMPER CENTRE PROTECTOR	1		\$347.50	\$ 347.50		\$ 347.50
12	REAR BUMPER SIDE PROTECTOR LH & RH	2		\$167.40	\$ 334.80		\$ 334.80

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
13	REVERSE SENSORS	4		\$463.90	\$ 1,855.60		\$ 1,855.60
14	REAR BUMPER REINFORCEMENT	1		\$948.20	\$ 948.20		\$ 948.20
15	REAR BUMPER REFLECTOR LH & RH	2		\$65.60	\$ 131.20		\$ 131.20
16	REAR END PANEL	1		\$1,194.90	\$ 1,194.90		\$ 1,194.90
17	REAR END PANEL TOP GARNISH	1		\$329.20	\$ 329.20		\$ 329.20
18	TAIL GATE INNER LOCK	1		\$288.35	\$ 288.35		\$ 288.35
19	TAIL GATE WEATHERSTRIP	1		\$226.10	\$ 226.10		\$ 226.10
20	REAR EXHAUST PIPE	1		\$2,698.60	\$ 2,698.60		\$ 2,698.60
21	SEALANT	1		\$60.00	\$ 60.00		\$ 60.00
SUBTOTAL					\$ 20,546.30	SUBTOTAL	\$ 20,546.30
GST 7%					\$ 1,438.24	GST 7%	\$ 1,438.24
TOTAL					\$ 21,984.54	TOTAL	\$ 21,984.54

REMARKS:

I AGREE TO THE REMARKS AND PRICE AS LISTED ABOVE.

FOR DICKSON AUTO CARE CENTRE PTE LTD

(CUSTOMER'S SIGNATURE AND
COMPANY STAMP)

(AUTHORISED SIGNATURE)

