



DICKSON GROUP
Your Trusted Automotive Solutionist

DICKSON AUTO CARE CENTRE PTE LTD
29 UBI ROAD 4, DICKSON AUTO CENTRE
SINGAPORE 408619
TEL: 6668 1122 | FAX: 6668 1123

SUPPLEMENTARY QUOTATION

QUOTATION FOR

NAME: MSIG Insurance (Singapore) Pte. Ltd
COMPANY NAME: MSIG Insurance (Singapore) Pte. Ltd
STREET ADDRESS: 4 Shenton Way, #21-01 SGX Centre Two
POSTAL CODE: Singapore 068807
PHONE: 6827 2888

DATE: 14/10/2022

REF: SNA9222X
VEHICLE NO.: SNA9222X
MAKE: BMW
MODEL: X5
PREPARED BY: POON

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
	<u>PARTS</u>						
1	REAR BUMPER BRACKET	1		\$253.70	\$ 253.70	bt✓	\$ 253.70
2	REVERSE SENSOR WIRING	1		\$132.30	\$ 132.30	cut✓	\$ 132.30
3	TAILGATE CONTROL UNIT F005V00833	1		\$605.20	\$ 605.20	nw✓	\$ 605.20
4	TAILGATE LOWER PANEL	1		\$2,420.30	\$ 2,420.30	bt✓	\$ 2,420.30
	<u>LABOUR</u>						3411.50
1	TO DO DIAGNOSTIC & REPROGRAM TAILGATE SYSTEM	1		\$280.00	\$280.00		\$ 150 280.00
SUBTOTAL					\$ 3,691.50	SUBTOTAL	\$ 3,691.50
GST 7%					\$ 258.41	GST 7%	\$ 258.41
TOTAL					\$ 3,949.91	TOTAL	\$ 3,949.91

REMARKS:

I AGREE TO THE REMARKS AND PRICE AS LISTED ABOVE.

FOR DICKSON AUTO CARE CENTRE PTE LTD

(CUSTOMER'S SIGNATURE AND
COMPANY STAMP)

(AUTHORISED SIGNATURE)



3443.25
3411.50
6854.75
10% - 6169.27
6169.27
1280
150
7599.27
41586050, 105 days