



The Motor Claims Department
M/s Lonpac Insurance Bhd
300 Beach Road, #17-04/07
The Concourse
Singapore 199555

File No : SH/2022/255/10/010/OD
Date : 21-October-2022

Supplementary estimated cost of repair for vehicle no: SKA6996B Toyota Estima
Policy No: =Z22VP05031418 Accident Date: 29.09.2022

Description	Quantity	Cost Price
Rear end panel lower trim	1	\$ 180.00 ✓
Rear keyless sensor	1	\$ 90.00 ✓
		\$ 270.00
Add 15%		\$ 40.50
		\$ 310.50
Remove rear cushion seat and trim cover		\$ 350.00 18d
		\$ 660.50