

COMFORTDELGRO ENGINEERING PTE LTD

SAS-KIV

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

LKK - Guo Qiang

DATE: 10.10.2022

MODEL: Hyundai Ioniq

INSURANCE: INCOME - (CL5)

VEHICLE NO.: SHA7282G

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
	Frt Fender RH <i>X Rep</i>	1		\$ 588.80	
	Frt Fender Blue-Drive RH <i>cut</i>	1		\$ 26.60	
	Frt Door Protector RH <i>cut</i>	1		\$ 186.20	
	Rocker Panel Garnish RH <i>X Rep</i>	1		\$ 290.00	
	Front Wheel Cap RH <i>cut</i>	1		\$ 346.40	
	SUB TOTAL			\$ 1,438.00	
	LESS 20%			\$ 287.60	
	DISCOUNTED TOTAL			\$ 1,150.40	
	Front Door ComfortDelGro RH <i>cut</i>	1		\$ 75.00	
	S/NETT LESS 10%			\$ 7.50	
	S/NETT TOTAL			\$ 67.50	
	Front Door Adv.Sticker RH <i>cut</i>	1		\$ 100.00	NETT
	Front Fender Adv.Sticker RH <i>cut</i>	1		\$ 100.00	NETT
	Rocker Panel Garnish Adv.Sticker RH <i>cut</i>	1		\$ 100.00	NETT
	PARTS TOTAL			\$ 1,517.90	
	Labour Charge				
	Panel Beating			\$ 800.00	
	Spray Painting Charge			\$ 900.00	
	Tuff Kote			\$ 60.00	
	TOTAL LABOUR			\$ 1,760.00	
	ESTIMATE TOTAL			\$ 3,277.90	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

2 Days.
4/5
Gme Key
10/10
4pm

-20%: 1550

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before later spray painting
- To display damaged parts during resurvey
- Parts price to be based on "no prejudice" basis
- Third party to be involved
- No illegal work to be carried out
- Supplier to be approved and is supplied by the Insurance Company

Acc
S