

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

Lim Tien Siong

59 Loyang Drive
Singapore 508969
Tel: 6214 8300**TP INSURER:**
CTPL**Tokio Marine Insurance Singapore Ltd (HQ)**

CL(S)

Singapore

LKK-

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	11/10/2022
Vehicle Reg. No.:	SHD4443M	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	08/11/2018
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEJU112140	Chassis No:	KMHC851CVKU115233
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	2,142.72
Miscellaneous Items	11.00
Labour	820.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,973.72
+ GST 7.00% (S\$)	208.16
Nett Amount (S\$)	3,181.88

This claim is handled by: LIM TIEN SIONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Lim Tien Siong

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Oct 2022)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHD4443M/11/10/2022 15:09

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER / ee	20.00	0.00	*459.40 FL
2	1		*REAR BUMPER CENTRE MOULDING / ee	20.00	0.00	*451.25 FL
3	1		*REAR BUMPER LOWER MOULDING X nn	20.00	0.00	*155.00 FL
4	1		*REAR BUMPER REINFORCEMENT X nn	20.00	0.00	*394.80 FL
5	2		*REAR BUMPER REINFORCEMENT BRKT RH / LH ?	20.00	0.00	*276.20 FL
6	1		*REAR BUMPER REFLECTOR RH / LH X nn	20.00	0.00	*41.45 FL
7	10		*REAR BUMPER CLIPS / abc	20.00	0.00	*22.00 FL
8	1		*REAR BUMPER FOGLAMP X nn	20.00	0.00	*201.50 FL
9	1		*REAR SMART KEY ANTENNA X nn	20.00	0.00	*40.50 FL
10	1		*REAR BUMPER MAT / abc	0.00	0.00	*50.00 F
11	1		*REVERSE SENSORS X nn	0.00	0.00	*180.00 F
12	1		*REAR BUMPER TOW COVER X nn	20.00	0.00	*98.80 FL
13	2		*REAR FENDER ADVERTISEMENT STICKER RH / LH / abc	0.00	0.00	*200.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,570.90
- List Item Discount on L Items (S\$)	428.18
Total Parts (S\$)	2,142.72

ComfortDelGro Engineering Pte Ltd/SHD4443M/11/10/2022 15:09. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

Lim Tien Siong

No Qty Particulars

Amount

Miscellaneous Items

1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	PANEL BEATING	New	350	400.00
2	SPRAY PAINTING	New	250	300.00
3	R/I REVERSE SENSORS	New	40	120.00
Gross Labour Cost (S\$)				820.00

ComfortDelGro Engineering Pte Ltd/SHD4443M/11/10/2022 15:09. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

2 Days.
4/5
Gm. Og
12/10
3pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price subject to confirmation
- Third party survey on "Without Prejudice" basis
- No third party survey allowed
- Supplier price subject to resurveyed and is subject to the insurance Company

Acknowledged by Repairer

Signature:

Date: