



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT

SOMPO INSURANCE SINGAPORE PL
50 RAFFLES PLACE #03-03 SINGAPORE LAND
TOWER SINGAPORE 048623

Ref: CS3/SMO22010062/Aqy3e2

Date: 17/01/2023

Code: SMO

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLR 1198U	Veh. Inspected	FW 6816G
Policy No.	D22MTRENT000394	Coverage (\$)	0.00
Claim No.	CMTD2203505/THE	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	12/10/2022

2. Vehicle Particulars & Condition


Make & Model	CFMOTO 400GT	c.c	400
Engine No.	HIDDEN	Year of Reg.	2022
Chassis No.	LCEPEL52N6000377	Colour	WHITE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	120/60 R17	ADRENO	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	160/60 R17	ADRENO	6 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.



5. General Information

Accident Date	28/09/2022	Inspect Date / Time	12/10/2022 (02:08 PM)
Survey held at	M 1 MOTORING 411 CHANGI ROAD SINGAPORE 419860		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
 B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
 THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
 C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
 D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500-\$4,500

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------

Report Ref No. CS3/SMO22010062/Aqy3e2

Inspected By

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.