



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2300970

INV Date 18/02/2023

Reference CC4/LPC22010068/Epa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. WC 292K
Insured Veh. XB 9549E
Claim No. 21/22/22/VC05/026403
Policy No. Z21VC05008854
Accident Date 29/09/2022
Inspection Date 12/10/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC22010068/Epa3q2 Date: 18/02/2023 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XB 9549E	Veh. Inspected	WC 292K	
Policy No.	Z21VC05008854	Coverage (\$)	0.00	
Claim No.	21/22/22/VC05/026403	Excess (\$)	0.00	
Assign From	ENG HUEY NI	Assign Date	12/10/2022	
2. Vehicle Particulars & Condition				
Make & Model	ISUZU CXH51S	c.c	14256	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	JALCXH51S67000088	Colour	BLUE	
Odometer	336739 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	BRIDGESTONE	4 mm	
L/H Front Tyre	295/80 R22.5	BRIDGESTONE	4 mm	
R/H Rear Tyre	295/80 R22.5	BRIDGESTONE	4 mm	
L/H Rear Tyre	295/80 R22.5	BRIDGESTONE	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/09/2022	Inspection Date	12/10/2022	
Survey held at	WTS ENGINEERING PTE LTD NO.8, GUL CIRCLE, SINGAPORE 629564.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. WC 292K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	RHS BUMPER TOP PLASTIC COVER	BROKEN	96.00	96.00
1	RHS FOOTPLATE ASSY	BROKEN	357.00	357.00
1	RHS CORNER PROTECTOR	NOT NECESSARY	108.00	-
1	PLASTIC FRONT MUDGUARD	BROKEN	156.80	156.80
1	RHS BUMPER BRACKET	DENTED	160.00	160.00
1	FRONT MUDGUARD BRACKET	BENT	120.00	120.00
1	RHS FOOTPLATE ASSY BRACKET	BENT	150.00	150.00
	LESS 10% DISCOUNT		-	-103.98
			1,147.80	935.82
	<u>LABOUR</u>			
	DISMANTLE & PLACE DAMAGED:PLASTIC FRONT MUDGUARD,FRONT MUDGUARD BRACKET,RHS BUMPER TOP PLASTIC COVER,RHS CORNER PROTECTOR,RHS FOOTPLATE ASSY,RHS FOOTPLATE ASSY BRACKET,RHS BUMPER BRACKET.		750.00	350.00
	PANEL BEATING ON BUMPER DAMAGED AREA.	NOT NECESSARY	350.00	-
	PUTTY AND SPRAY PAINTING ON THE DAMAGED PARTS.		600.00	300.00
			1,700.00	650.00
GRAND TOTAL			2,847.80	1,585.82
RECOMMENDED COST OF REPAIRS				1,585.82

Report Ref No. CC4/LPC22010068/Epa3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. WC 292K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. WC 292K

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

