

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte.
Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Hor, Yinrul

Date: 21 Oct 2022

Preliminary Advice

Vehicle No	: SLM5505S	Accident Date	: 08/10/2022
Make	: AUDI S3	Policy No.	: 2100504302
Assignment Date	: 12/10/2022	Excess	: S\$2,000.00
Date of Inspection	: 12/10/2022	Est. Duration of Repair	: 11
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 48,816.00	(Estimate \$48,508.00 + Supplementary \$308.00)
Revised Amount	:S\$ 24,517.50	
Check Items (Estimated)	:S\$ 7,648.00	
Total	:S\$ 32,165.50	
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value	:S\$ 148,000.00
COE / PARF Rebate	:S\$ 60,851.00
Salvage Value	:S\$
Margin for Repair	:S\$ 87,149.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.