

Xin Yu (LKK Auto)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Tuesday, November 29, 2022 5:47 PM
To: Steve Chen (LKK Auto); Xin Yu (LKK Auto); SUR; Carrine Leong; jiayee.yap@premiumauto.com.sg; Chang Chee Sing
Subject: FINAL REVISION - SJT9963M - OD AIG - SURVEYED 12 OCT 22
Attachments: WhatsApp Image 2022-10-25 at 1.05.08 PM (1).jpeg; WhatsApp Image 2022-10-25 at 1.05.08 PM (2).jpeg; WhatsApp Image 2022-10-25 at 1.05.09 PM (1).jpeg; WhatsApp Image 2022-10-25 at 1.05.07 PM.jpeg; WhatsApp Image 2022-10-25 at 1.05.08 PM.jpeg; WhatsApp Image 2022-10-25 at 1.05.09 PM.jpeg; WhatsApp Image 2022-10-25 at 1.05.10 PM.jpeg; WhatsApp Image 2022-10-25 at 1.05.10 PM (1).jpeg; PA08752022 - SJT 9963 M - AUDI A4 SEDAN 2.0 TFSI - FRONT - AIG (OD) + SUPP.xlsx; RE-SURVEY SJT9963M.pdf

Hi Steve and all,

Revised estimate, re-survey docs and photographs attached.

Please confirm repair cost of \$31,820.88 @ 9 days exclude 1 Sunday.

Your early closure is appreciated.

Best regards - Johnny Boo