

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg




Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0875/2022/EQ 19-Oct-22 CHANG 1 of 1 SJT 9963 M AUDI A4 SEDAN 2.0 TFSI
Quantity	Description	Unit Price	Amount
Labours			
1	TO REPAIR BOTH FRONT FENDERS. 1/2	\$ 700.00	250
2	TO RESPRAY BOTH FRONT FENDERS. 1	\$ 2,100.00	1100
Parts			
1	AIR GUIDE GRILLE - RH CUT 1	\$ 151.00	#120.40 ✓
GRAND TOTAL		\$ 2,951.00	

For Premium Automobiles Pte Ltd

Stew CLKK1
23/10/22



Authorised Signature

Replaced lock cylinder & repair both fenders + 4 days

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJT 9963 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	RECOMMENDATION
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N S 480.00	✓
2	TO REMOVE AND TRANSFER BOTH FRONT HEADLIGHTS CONTROL UNIT AND POWER MODULES. 25% 1/2	S/N S 700.00	50%
3	TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, CHARGED AIR COOLER, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM/REGAS AND TO PRESSURISE COOLING SYSTEM	S/N S 1,200.00	✓
2.5 4	TO DISMANTLE FRONT BUMPER AND BONNET. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW FRONT BUMPER, BOTH HEADLIGHTS AND BONNET. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. 2 x 55%	4,200.00	1250 1200 + 1250 = 2,500 ✓
5	TO RESPRAY FRONT BUMPER AND BONNET. 55% 1/2	S 1,800.00	1/100
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N S 192.00	✓
TOTAL LABOUR CHARGES		: S 8,572.00	

+ 8 days ✓
4

Car in 18/10/22 wp. 45555

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHA@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Bendi

AIG - Steve
- 4 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJT 9963 M

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & RICES		REMARKS
			S/NETT		
1	FRONT BUMPER / OK	1	\$	2,377.00	1901.60
2	FRONT BUMPER FIXING PARTS X	1	\$	612.00 X nn	
3	FRONT BUMPER GRILLE - CENTER ? - BR	1	\$	219.00 X nn	
4	RADIATOR GRILLE / OK	1	\$	1,478.00	1182.40
5	FRONT PARKING AID SENSOR - INNER / OUTER ?	2	\$	531.00 X nn	
6	FRONT PARKING AID SEAL RING / OK	4	\$	10.00	8.00
7	FRONT BUMPER FOAM FILLER PIECE ? - BR	1	\$	139.00	110.80
8	FRONT BUMPER REINFORCEMENT BEAM ?	1	\$	899.00 X nn	
9	FRONT REINFORCEMENT BEAM SUPPORT - LH / RH ? - BR (2)	2	\$	64.00	51.04
10	FRONT BUMPER BRACKET - CENTER / OK	1	\$	154.00	122.80
11	FRONT REINFORCEMENT BEAM BRACKET - LH / RH ?	2	\$	508.00 X nn	
12	FRONT BUMPER TOP COVER / OK	1	\$	143.00	114.00
13	CAUTION SIGN STICKER - OK	1	\$	16.00	12.40
14	AIR CONDITIONER STICKER - OK	1	\$	9.00	6.64
15	BONNET / OK	1	\$	3,425.00	2740.00
16	BONNET ATTACHMENT PARTS X	1	\$	431.00 X nn	
17	BONNET IMPACT PROTECTION - CENTER / LH / RH / OK	3	\$	93.00	73.20
18	BONNET HINGE - LH / RH ?	2	\$	680.00 X nn	
19	BONNET STRIKER - LH / RH ?	2	\$	112.00 X nn	
20	BONNET LOCK - LH / RH ?	2	\$	455.00 X nn	
SUB TOTAL SPARE PARTS		:	\$	<u>12,355.00</u>	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJT 9963 M

			DAMAGED PARTS :		RICE
S/N	PARTS DESCRIPTION	QTY	S/NETT	EMARK	
21	BONNET BOWDEN CABLE - CENTER ✓ ST	1 \$	64.00	50.56	
22	BONNET RELEASE CABLE ?	1 \$	64.00	50.56 ✓ dis	
23	HEADLIGHT - LH / RH ✓ BR	2 \$	16,588.00	13,270.40	
24	LOCK CARRIER ? - BR	1 \$	1,478.00	901.60	
25	RADIATOR AIR GUIDE - LH INNER ? - BR	1 \$	32.00	25.60	
26	RADIATOR AIR GUIDE - LH OUTER ? - BR	1 \$	14.00	10.88	
27	RADIATOR AIR GUIDE - RH INNER ? - BR	1 \$	32.00	25.60	
28	RADIATOR AIR GUIDE - RH OUTER ? - BR	1 \$	14.00	10.88	
29	RADIATOR AIR GUIDE - CENTER ?	1 \$	19.00 X nh		
30	CHARGE AIR COOLER ?	1 \$	654.00 X nh		
31	A/C CONDENSER ✓ ON	1 \$	683.00	546.00	
32	A/C CONDENSOR O - RING ?	1 \$	13.00 X nh		
33	A/C CONDENSOR SEAL RING ?	1 \$	12.00	9.44 ✓ dis	
34	A/C PRESSURE SENSOR ?	1 \$	206.00 X nh		
35	A/C HIGH-PRESSURE SWITCH SAFETY SWITCH VALVE ?	1 \$	53.00 X nh		
36	RADIATOR ? - ST	1 \$	1,013.00	810.40	
37	READY-MIX COOLANT ? - ncc	4 \$	198.00	237.12	
38	RADIATOR FAN RING ?	1 \$	292.00 X nh		
39	RADIATOR FAN CONTROL UNIT ? - ST	1 \$	2,489.00	1991.20	
40	FRONT NO PLATE ✓ ST	S/N \$	60.00	60.00	
41	SUNDRIES ?	\$	400.00	55.36 ✓ ncc	
TOTAL SPARE PARTS		:	\$ 36,733.00		
TOTAL LABOUR CHARGES		:	\$ 8,572.00		
GRAND TOTAL		:	\$ 45,305.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

Steve (LKK)
12/12/11, 12/11/11
00. M1 AC
EXCESS?
PIP
By RL 11. 7 days

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT