

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Hor, Yinrul

Date: 20 Oct 2022

Preliminary Advice

Vehicle No	: SJT9963M	Accident Date	: 08/10/2022
Make	: AUDI A4	Policy No.	: 1800080001
Assignment Date	: 12/10/2022	Excess	: S\$1,300.00
Date of Inspection	: 12/10/2022	Est. Duration of Repair	: 08 days
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	48,256.00 (Est \$45,305.00 + Supp \$2,951.00)
Revised Amount	:S\$	31,073.00 (Incl. Supp \$1,501.00)
Check Items (Estimated)	:S\$	10,590.00
Total	:S\$	41,663.00 (Incl. Supp \$1,501.00)
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	125,000.00
COE / PARF Rebate	:S\$	46,968.00
Salvage Value	:S\$	
Margin for Repair	:S\$	78,032.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Kindly approve on Supplementary.
- Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.