

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: HL Assurance Pte Ltd
11 Keppel Road
#11-01 ABI Plaza
Singapore 089057From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: ALANO Ana Maria Velarde

Date: 14 Oct 2022

Preliminary Advice

| | | | |
|--------------------|---|-------------------------|--------------|
| Vehicle No | : SLH2982T | Accident Date | : 10/10/2022 |
| Make | : BMW 216D | Policy No. | : MP314637 |
| Assignment Date | : 12/10/2022 | Excess | : S\$600.00 |
| Date of Inspection | : 14/10/2022 | Est. Duration of Repair | : 3 |
| Inspection At | : ACCORD AUTO SERVICES PTE LTD (HQ) 10 ANG MO KIO IND PARK 2A #03-11, AMK AUTO POINT SINGAPORE 568047 | | |

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 3,417.31 |
| Revised Amount | :S\$ | 3,117.31 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 3,117.31 |

Lump Sum Repair :S\$

Total Loss Consideration

| | | |
|--------------------|------|-----------|
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | 73,000.00 |
| COE / PARF Rebate | :S\$ | 38,341.00 |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | 34,659.00 |

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :Vehicle repair on Lump Sum basis
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.