

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ERGO Insurance Pte. Ltd.
8 Temasek Boulevard, #04-01 Suntec Tower Three
Singapore 038988

Our File No: CS4/EGI22010095/RCY3M4**Date:** 22/11/2022**REFERENCE**

Insured/Claimant: AEROMAC ENGINEERING PTE LTD Policy No: DMCG21010781
Date of Loss: 10/10/2022 Nature of Claim: OD Claim No: CDMCG22002131

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBA9564B**
Make & Model: TOYOTA DYNA 150 MANUAL, 3.0 D (M) Engine No: 1KD1804193
Reg. Date: 28/04/2008 (Man. Year: 2008) Chassis No: JTFAT35Y303001743
Colour: Grey Odometer: 0 km
Engine Capacity: 2982 cc
Market Value/New Car Price: S\$3,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/75 R15C Rear Tyre Size: 155 R12C (D/D)
Front Left Side: Kenda 7 mm Rear Left Side: Kenda 5/5 mm
Front Right Side: Kenda 7 mm Rear Right Side: Kenda 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,000.00	0.00	15,000.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	15,000.00	0.00	15,000.00	100.00

INSPECTION

Date of Assignment: 12/10/2022 Present Location: Forza Autohaus Pte Ltd (HQ)
Forza Autohaus Pte Ltd (HQ)
Date Inspected: 13/10/2022 Inspected At: No.39 Woodlands Close, #01-34/35,
Mega@Woodlands
Singapore 737856
Estimated Period of Repair: 0.0 days

Adjuster: MOHD RASUL**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$3,000.00
OMV :	\$24,243.00
PARF Rebate (1) :	\$0.00
Quota Premium Paid :	\$23,496.00
COE Rebate (2) :	\$1,762.00
Total Rebate (1) + (2) = :	\$1,762.00

The total amount incurred will be Market Value \$3,000.00 minus Total Rebate \$1,762.00 = \$1,238.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Reference

Part Source:	(Last Synchronised: 22 Nov 2022)	
Parts:	N/A	TOYOTA DYNA 150 MANUAL 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBA9564B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*VEHICLE IS BEYOND ECONOMICAL REPAIR (RECOMMEND FOR TOTAL LOSS)		15,000.00 F	*- F
						F=Franchise part.
				Total Parts (\$\$)	15,000.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >