

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard  
#04-01 Suntec Tower Three  
Singapore 038988

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Senthilan Dillen Selvarajoo

Date: 17 Oct 2022

## **Preliminary Advice**

Vehicle No	: GBA9564B	Accident Date	: 10/10/2022
Make	: TOYOTA DYNA 150	Policy No.	: DMCG21010781
Assignment Date	: 12/10/2022	Excess	: S\$0.00
Date of Inspection	: 13/10/2022	Est. Duration of Repair	:
Inspection At	: FORZA AUTOHAUS PTE. LTD.		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,000.00
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	

Lump Sum Repair	:S\$
-----------------	------

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	3,000.00
COE / PARF Rebate	:S\$	1,762.00
Salvage Value	:S\$	
Margin for Repair	:S\$	1,238.00

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( X ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Vehicle pending for investigation.