



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CS3/CTI22000889/Gvy3e2-1 Date: 14/11/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	CB 7554B	Veh. Inspected	SKD 3630K	
Policy No.	DMB1SNW00011502102	Coverage (\$)	0.00	
Claim No.	SNM22D200610/C02	Excess (\$)	0.00	
Assign From	JACQUELINE TAN	Assign Date	10/10/2022	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 335i 3.0L	c.c	2979	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	WBADX72040E668399	Colour	YELLOW	
Odometer	130847 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/35Z R19	MICHELIN	6 mm	
L/H Front Tyre	235/35Z R19	MICHELIN	6 mm	
R/H Rear Tyre	235/35Z R19	MICHELIN	6 mm	
L/H Rear Tyre	235/35Z R19	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/01/2022	Inspection Date	25/01/2022	
Survey held at	GARAGE 13 PTE LTD 8 KAKI BUKIT AVE 4 #03-46 PREMIER SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	