

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241

Fax: (65) 6741 7276

RCB No: 53231488C

GST Reg No : 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 11/10/2022

Estimated repair cost for vehicle no: SMF1710S TOYOTA COROLLA AXIO 1.5X A

CHASSIS: NZE1416112013 (2008)

13/10/2022

TP Liberty

S/N	Qty	Items	U/price	Amount
1	1	FRONT BUMPER <i>dent</i>	\$864.00	\$864.00 <i>485</i>
2	1	FRONT BUMPER REINFORCEMENT <i>new</i>	\$385.00	\$385.00 <i>+</i>
3	1	LH FRONT BUMPER FOG LAMP COVER <i>new</i>	\$95.00	\$95.00 <i>+</i>
4	1	LH FRONT BUMPER SIDE RETAINER <i>dent</i>	\$58.00	\$58.00 <i>✓</i>
5	1	LH FRONT FENDER <i>Dented.</i>	\$735.00	\$735.00 <i>589</i>
6	1	LH FRONT FENDER INNER COWLING <i>new</i>	\$176.00	\$176.00 <i>✓</i>
7	1	LH FRONT FENDER LAMP <i>new</i>	\$48.00	\$48.00 <i>+</i>
8	1	BONNET <i>Repair</i>	\$951.00	\$951.00 <i>+</i>
9	1	LH FRONT HEADLAMP <i>crack d</i>	\$890.00	\$890.00 <i>✓</i>
10	1	LH FRONT HEADLAMP LOWER BRACKET <i>new</i>	\$76.00	\$76.00 <i>+</i>
11	1	LH FRONT LOWER ARM <i>Bent.</i>	\$428.00	\$428.00 <i>365</i>
12	1	LH FRONT KNUCKLER ARM <i>Damaged</i>	\$548.00	\$548.00 <i>✓</i>
13	1	LH FRONT KNUCKLER ARM BEARING <i>dent</i>	\$289.00	\$289.00 <i>✓</i>
14	1	LH FRONT SHOCK ABSORBER <i>new</i>	\$544.00	\$544.00 <i>X.</i>

TOTAL : \$6,087.00

LESS 25 % \$1,521.75

SUB-TOTAL : \$4,565.25

3410

2557.50

SMF1710S TOYOTA COROLLA AXIO

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	FRONT BUMPER CLIPS <i>new</i>	\$80.00	\$80.00 50
2	1	LH FRONT FENDER INNER COWLING CLIPS <i>new</i>	\$80.00	\$80.00 30
3	1	LH FRONT TYRE <i>new</i>	\$320.00	\$320.00 +
4	1	LH FRONT SPORT RIM <i>cut</i>	\$550.00	\$550.00 400

480

TOTAL: \$1,030.00

TOTAL PARTS: \$5,595.25

Labour charges

1	LABOUR FOR PANEL BEATING	\$1,000.00	400
2	LABOUR FOR SPRAYPAINTING	\$800.00	400
3	WIRING CHECK	\$80.00	30
4	LABOUR FOR REMOVE & RENEW LH FRONT UNDER CARRIAGE	\$250.00	150
5	TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS	\$300.00	40
6	TO CONDUCT WHEEL ALINGMENT	\$150.00	80

Subtotal :- \$2,580.00

Total:- \$8,175.25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
2/s 13/10/22
05hys

total: 4137.50

C/S 3:31K

3:31C