



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP22010158/Rvy3m4 Date: 28/04/2023 Code: LIP	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SDN 9813R	Veh. Inspected	SML 4660B	
Policy No.		Coverage (\$)	0.00	
Claim No.	AVS22/2850	Excess (\$)	0.00	
Assign From	ANDY SEAH	Assign Date	12/10/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA VIOS 1.5 E (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	MR2B23F3001174000	Colour	BLUE	
Odometer	206431 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/60R15	WEST LAKE	6 mm	
L/H Front Tyre	185/60R15	WEST LAKE	6 mm	
R/H Rear Tyre	185/60R15	WEST LAKE	6 mm	
L/H Rear Tyre	185/60R15	WEST LAKE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	07/10/2022	Inspection Date	14/10/2022	
Survey held at	MY CAR CONSULTANT PTE LTD 60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869			
<b>5a. Remarks</b>				
A)REGISTRATION DATE: 22 MAY 2019 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	