

Our Job Ref No : 305531721
Date : 04/10/22

COMFORTDELGRO
ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : Mr Taufikh
Vehicle Reg No. : SHC3837Y

Fax :

28.09.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: **CHINA TAIPING** -- **SLJ5965M**
2. The finalized amount shall be:
 - (a) Spare Parts after List discount ~~\$1,925.92~~ \$1,325.93
 - (b) Labour Charges ~~\$1,395.00~~ \$1,395.00
 - Total for Part-By-Part Repair Cost** ~~\$2,720.92~~ \$2,720.93
 - (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost \$0.00


3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : Ms. Loke YY
Tel : 62148355
Fax : 65468156

Signature : 
Name : Taufikh
Date : 02/11/2022

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305531721
 REGN NO : SHC3837Y
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID(G4A)
 DATE OF REGN : 05.12.2019
 DATE/TIME IN : 28.09.2022 19:35
 ACCIDENT DATE : 28.09.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0302-2712-G	COVER REAR BUMPER#	1	503.04	25.00	377.28
0002	04-01-0302-2713-G	GUARD REAR BUMPER CENTER	1	654.96	25.00	491.22
0003	04-01-0302-2715-G	COVER RR BUMPER -TOW HOOK	1	82.70	25.00	62.02
0004	04-01-0302-2267-G	BUMPER PIECE	10	22.00	25.00	16.50
0005	04-01-0302-2270-G	PLATE-BACK DOOR NAME (HYB	1	62.14	25.00	46.60
0006	04-01-0302-2271-G	PLATE-BACK DOOR NAME (PRI	1	62.14	25.00	46.60
0007	28-01-0302-2015-A	REAR BONNET COMFORTDELGRO	1	30.00	2.50-	30.00
0008	28-01-0302-0006-A	REAR BOOT 65521111 CTPL	1	30.00	0.25	30.00
0009	28-01-9999-2034-A	ZIG BOOK NOW APP LOGO REA	1	40.00	0.03-	40.00
0010	04-01-0302-1150-A	BUMPER PROTECTOR MAT	1	50.00	0.00	50.00
0011	09-01-0302-2005-A	REVERSE SENSOR ASSY XX	1	135.70	0.00	135.70

SUB-TOTAL : 1,325.92

JOB NATURE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305531721
REGN NO : SHC3837Y
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID
DATE OF REGN : 05.12.2019
DATE/TIME IN : 28.09.2022 19:3
ACCIDENT DATE : 28.09.2022

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0000 PB	PANEL BEATING SHC3837Y -TP			525.00		
0001 SP	SPRAYPAINT CHARGE			600.00		
0002 23-01	TOWING FEE			60.00		
0003 17-01	CHECK ALL LIGHTING			30.00		
0004 20-00	TUFF COAT ON AFFECTED PARTS.			30.00		
0005 L	REMOVE/ REFIX RR WINDSCREEN GLASS			120.00		
0006 20-204	REMOVE/REFIX REVERSE SENSOR			30.00		
SUB-TOTAL						: 1,395.00
TOTAL						: 2,720.92

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :