



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HENG KEE WORKSHOP		Ref:	CS/TP22010179/Acm4
1033 EUNOS AVENUE 5A #01-31 EUNOS INDUSTRIAL ESTATE SINGAPORE 409703		Date:	06/01/2023
ON BEHALF OF LUA ENG SENG		Code:	TP483
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.		Veh. Inspected	SMH 3134G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	14/10/2022
2. Vehicle Particulars & Condition			
Make & Model	MAZDA 6	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JM6GL1072K0311705	Colour	GREY
Odometer	67007 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/55 R17	YOKOHAMA	6 mm
L/H Front Tyre	225/55 R17	YOKOHAMA	6 mm
R/H Rear Tyre	225/55 R17	YOKOHAMA	6 mm
L/H Rear Tyre	225/55 R17	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	06/10/2022	Inspection Date	13/10/2022
Survey held at	HENG KEE WORKSHOP 1033 EUNOS AVENUE 5A #01-31 EUNOS INDUSTRIAL ESTATE SINGAPORE 409703		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	