

Repair Estimate


Not Withheld
11 By 811, 200h
Pickup After Repair
5 days

Fulco Autocare Pte Ltd

176 Sin Ming Drive #03-02 Sin Ming Autocare Singapore 575721
Tel: (65) 6552 0302 Fax: (65) 6552 0780 Email: admin@fulcoautocare.com

Make/Model: ASTON MARTIN DB9
Engine/Chassis No.: SCFEEBAC5AGC13700
Date of accident:
Damaged area: O/S front

Date: 17/10/2022
Claim Type: TP
VRN: SLJ729L



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Upper arm o/s	1	\$ 1,008.00	\$ 1,008.00
2	Lower arm o/s	1	\$ 1,372.00	\$ 1,372.00
3	Wheel carrier o/s	1	\$ 826.00	\$ 826.00
4	Wheel hub assy o/s	1	\$ 896.00	\$ 896.00
5	Shock absorber o/s	1	\$ 2,660.00	\$ 2,660.00
6	Front fender o/s	1	\$ 5,040.00	\$ 5,040.00
Subtotal				\$ 11,802.00
List discount				10.00%
Total				\$ 10,621.80

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front fender liner o/s clips	12	\$ 6.50	\$ 78.00
2	Front alloy wheel o/s -710 2250	1	\$ 2,972.00	\$ 2,972.00
3	Front tyre o/s	1	\$ 780.00	\$ 780.00
4	Sundries	1	\$ 50.00	\$ 50.00
Total				\$ 3,880.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew the accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	7	\$ 1,400.00
2	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check functions.	0.5	\$ 100.00
3	Supply spray paint material and necessary items to respray affected area / panel.	6	\$ 1,200.00
4	To rust proof all affected portions after repair.	0.5	\$ 100.00
5	To remove and refit n/s front undercarriage for replacement of parts.	4	\$ 800.00
6	To remove and replace n/s front tyre & rim. To perform tyre balancing.	1.5	\$ 300.00
7	To conduct computerized wheel alignment of the following:	0.75	\$ 150.00
Total labour			\$ 4,050.00
Estimate Grand Total			\$ 18,551.80

LKK Auto Consultants hence notify

• To resurvey before/after spray painting

• To display damaged cost of repair

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and

is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: