

SERVICE ESTIMATE

| | |
|---|---|
| 0 - C00010 | SL: CHINA TAIPING INSURANCE (SINGAPORE) |
| CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD | GST Reg.No:M28920628X |
| 3 ANSON ROAD | Inv.No. . : B&P 0 Page 1 |
| #16-00, SPRINGLEAF TOWER | Inv.date. : 25/11/2022 |
| SINGAPORE 079909 | WIP No. . : 45511 |
| | Veh.In/Out: 22/11/2022 |
| | *Tel.No. . : 63896111 |
| | Reg.No. . : SFP1777E |
| Closed by : Paul Ong Qing Yong | Reg.date . : 29/11/2017 |
| Svc Consultant : ACC | Mileage . . : 108,618 |
| Remarks : Ms Low Su Lin Yvonne | Chassis No: SAJAB4AN8JCP25671 |

| Op.No | Description | Mech Qty | Price | Disc% | Pkg | Amount | G |
|-------|---|-----------------|---------------------|-------|-----|---------------------|-----------------|
| 802 | TO REPLACE REAR BUMPER, VALANCE REAR, REAR LAMP LH, REMOVE, REFIT BOOTLID | 0 | 1950.00 | 0 | | 1,950.00 | S |
| 800 | TO SPRAYPAINT ON REAR BUMPER, BOOTLID | 0 | 2000.00 | 0 | | 2,000.00 | S |
| 280 | TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES | 0 | 621.00 | 0 | | 621.00 | S |
| | COVER-BUMPER REAR | 1.0 EA | 1325.30 | 10 | | 1,192.77 | S |
| | PANEL-VALANC | 1.0 EA | 609.80 | 10 | | 548.82 | S |
| | TOW COVER REAR XE | 1.0 EA | 37.20 | 10 | | 33.48 | S |
| | BADGE REAR "XE" | 1.0 EA | 136.90 | 10 | | 123.21 | S |
| | BADGE | 1.0 EA | 250.60 | 10 | | 225.54 | S |
| | BADGE | 1.0 EA | 131.60 | 10 | | 118.44 | S |
| | LAMP-TAIL LH | 1.0 EA | 593.40 | 10 | | 534.06 | S |
| | FOG LAMP REAR LH XE | 1.0 EA | 443.40 | 10 | | 399.06 | S |
| | BUMPER BEAM REAR XE | 1.0 EA | 753.50 | 10 | | 678.15 | S |
| | | | Gross Total. | | | 8,424.53 | |
| | Labour Total | 4,571.00 | | | | Net..... | 8,424.53 |
| | Parts Total | 3,853.53 | | | | GST @ 7.0% | 589.72 |
| | Package Total | 0.00 | | | | Total..... | 9,014.25 |
| | | | | | | Paid..... | 0.00 |
| | | | | | | Please Pay.. | 9,014.25 |

GST: S=StdRated; O=OutOfScope; Z=ZeroRated