



YSK AUTO WORKSHOP

No. 1 Kaki Bukit Avenue 6 @Autobay, #01-71 Singapore 417883
UEN 53311047E

TO: AIG INSURANCE
AIG Building
78 Shenton Way, Level 1
Singapore 079120

C/O: LKK Auto Consultants Pte Ltd
Blk 51, Paya Ubi Industrial Park,
Ubi Avenue 1, #02-25 | S(408933)

REPAIR BILL

Invoice : **202212-0193**
Date : 31/12/2022
Vehicle/ Make Model : HONDA FREED, 1496cc
Accident Date : 11/10/2022 16:00 (SGT)
Accident Location : JUNCTION OF CLEMENT RD/UPP BUKIT TIMAH RD

Particular	Amount
COST OF REPAIR	\$5,200.00

Total S\$: 5,200.00

=====

SAY TOTAL SINGAPORE DOLLARS: FIVE THOUSAND TWO HUNDRED ONLY.



YSK Auto Workshop