



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0883/2022/EQ
DATE : 13-Oct-22
WIP : 46017

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 14/10/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR BENJAMIN TOH LIK HONG
ADDRESS : 480 SIGLAP ROAD
#01-84, FLAMINGO VALLEY
SINGAPORE 454855
TELEPHONE : HP +65 81210900
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210142500
VEHICLE NO : **SLX 7011 D**
MODEL CODE : AUDI Q3 SPORTBACK 1.4 TFS
MODEL YEAR : 23/11/2021
ENGINE NO : CZD C54128
CHASSIS NO : WAUZZZF3XN1038143
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 13-Oct-22
PLACE OF ACCIDENT : IN FRONT OF THE RAFFLES HOTEL DRIVEWAY



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLX 7011 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$ 360.00 ✓	
2	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 800.00 280	
3	TO DISMANTLE AND RENEW REAR BUMPER, RHS REAR DOOR AND RHS FRONT DOOR. TO REPAIR RHS REAR FENDER, RHS SILL PANEL AND DOOR ENTRANCES. RE-ORGANIZE CRASH MANAGEMENT CRASH COMPONENTS. REINSTALL ALL PARTS REMOVED. ✓	\$ 4,000.00 1500	
4	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS REAR DOOR, RHS FRONT DOOR, DOOR HINGES, 2 DOOR COVER, DOOR ENTRANCES, RHS SILL PANEL AND BOTH REAR WHEEL ARCH TRIMS. ✓✓	\$ 6,500.00 3000.	$4 \times 550 = 2200$ $Acc \times 2 = 400$ $Door Protection \times 2 = 400$ <hr/> 3000.
5	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00 ✓	
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>12,132.00</u>	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLX 7011 D

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Rep's</i>	1	\$ 1,738.00	X
2	REAR BUMPER SPOILER <i>lt</i>	1	\$ 510.00	✓ 408
3	REAR BUMPER GRILLE - RH <i>neu</i>	1	\$ 170.00	X
4	REAR PARKING AID SENSOR SUPPORT - RH <i>neu</i>	1	\$ 28.00	+
5	REAR BUMPER ADAPTER - RH <i>neu</i>	1	\$ 95.00	+
6	REAR BUMPER CROSS REINFORCEMENT - CENTER <i>neu</i>	1	\$ 108.00	+
7	REAR BUMPER BRACKET	1	\$ 53.00	+
8	REAR BUMPER REFLECTOR - RH <i>neu</i>	1	\$ 46.00	+
9	REAR BUMPER GUIDE SECTION - RH	1	\$ 71.00	✓
10	REAR UNDERBODY TRIM - RH <i>neu</i>	1	\$ 58.00	+
11	REAR WHEEL COVER - LH / RH <i>neu</i>	2	\$ 1,132.00	✓ 904.80
12	REAR DOOR - RH <i>Dist'd</i>	1	\$ 3,028.00	✓ 2422.40
13	REAR OUTER DOOR SEAL - RH <i>neu</i>	1	\$ 151.00	✓ 120.40
14	REAR DOOR CATCH <i>Dist'd</i>	1	\$ 134.00	✓ 106.80
15	REAR INNER DOOR SEAL <i>neu</i>	1	\$ 213.00	+
16	REAR SILL PANEL SEAL - RH <i>neu</i>	1	\$ 151.00	+
17	REAR DOOR COVER - RH <i>Dist'd</i>	1	\$ 368.00	✓ 294
18	REAR DOOR SIDE MEMBER TRIM - RH <i>neu</i>	1	\$ 189.00	+
19	REAR WHEEL SPOILER - RH <i>neu</i>	1	\$ 44.00	+
20	REAR WHEEL HOUSING LINER - RH <i>neu</i>	1	\$ 262.00	+
SUB TOTAL SPARE PARTS			\$ 8,549.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLX 7011 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT DOOR - RH <i>Reps</i>	1	\$ 3,028.00	+
22	FRONT OUTER DOOR SEAL - RH <i>new</i>	1	\$ 185.00	+
23	FRONT DOOR CATCH <i>new</i>	1	\$ 134.00	+
24	FRONT DOOR COVER - RH <i>delud</i>	1	\$ 390.00	✓ 312
25	FRONT DOOR HINGE HALF -UPPER PART - RH LOWER <i>part</i>	1	\$ 53.00	+
26	FRONT DOOR HINGE HALF - LOWER PART - RH LOWER <i>n</i>	1	\$ 49.00	+
27	REAR ALUMINIUM RIM <i>cut</i>	1	\$ 1,414.00	✓ 1131.20
28	REAR ALUMINIUM RIM RUBBER VALVE <i>new</i>	1	\$ 4.00	+
29	SUNDRIES <i>new</i>		\$ 400.00	? ✓ 25.20
TOTAL SPARE PARTS		:	\$ 14,206.00	
TOTAL LABOUR CHARGES		:	\$ 12,132.00	
GRAND TOTAL		:	\$ 26,338.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian G*
SURVEYED DATE : *14/10/22*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 07 Days* *R/S*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT