

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Hor, Yinrul

Date: 15 Feb 2023

Preliminary Advice

Vehicle No	: SLX7011D	Accident Date	: 13/10/2022
Make	: AUDI Q3 SPORTBACK	Policy No.	: 7210142500
Assignment Date	: 17/10/2022	Excess	: S\$400.00
Date of Inspection	: 14/10/2022	Est. Duration of Repair	: 7
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	26,601.00 (inclusive supp \$263.00)
Revised Amount	:S\$	11,547.20
Check Items (Estimated)	:S\$	0.00
Total	:S\$	11,547.20

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	180,000.00
COE / PARF Rebate	:S\$	99,083.00
Salvage Value	:S\$	
Margin for Repair	:S\$	80,917.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :Kindly approve on supplementary