



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705		Ref: CS/SMR22010254/Evy3e2 Date: 06/12/2022 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 6159X	Veh. Inspected	SNC 3328D
Policy No.		Coverage (\$)	0.00
Claim No.	TAX/10/22/2028	Excess (\$)	0.00
Assign From	ANA	Assign Date	14/10/2022
2. Vehicle Particulars & Condition			
Make & Model	KIA CERATO	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	KNAF5416MM5097854	Colour	RED
Odometer	24338 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	GOODYEAR	4 mm
L/H Front Tyre	205/55 R16	GOODYEAR	4 mm
R/H Rear Tyre	205/55 R16	GOODYEAR	4 mm
L/H Rear Tyre	205/55 R16	GOODYEAR	4 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	10/10/2022	Inspection Date	01/11/2022
Survey held at	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	